

RC steel identified

Low impact on neighbouring activitie easily secured from public.

Flat, dry paddock or sealed/ metalled Vehicle Access track or road Required Minor **Vegetation Control** Dairy Farm Property Usage TSC Bridge/ Culverts YES

Foundation Connection Type Cell Coverage Average Insulator Type/ Condition COMPOSITE



No access directly to structure, walk 300 metres

LSD - missing

cpi - no cpi in Fiji, added in to show phasing

Tower base needs clearing Legs painted with CTE about 400mm above ground level

Minor construction damage to steel member main horizontal coming of B-Leg

WAI-VUD-A0021

69-1

HSG+3

+1, +2, +1, -1

YES

0

154

8%

83%

12

127

Light ZCP through out tower

Device Position Description

Contract number

Body - size

Body Extn - size

Legs - size

Paint Type Tower Area m²


MAD Tower Area m²

Spot Blast m²


Dross noted throughout tower

Top chord coming off B-Leg minor construction damage, top cross arm.

Minor galv flaw on top cross arm floor steel, at end of cross arm, diagonal.

















LANDOWNER DETAILS		INSPECTION TEAM LUMEN		Date	GPS COORDINATES (WGS84)					
				9/02/2024						
LandOwner	Unknown	Inspector-Tower	Karl Formo		LATITUDE	17°42'38.16"S				
TowerAccess	Unknown	Inspector-Ground	Karl Formo		LONGITUDE	177°30'9.36"E				
ContactName	Unknown	Draft Report	R. Glover	24/04/2023						
ContactPhone	Unknown	Report Review								



				_			
WAI-VUD A Paint Towers 19/20		SCALE FO		LDER			
WAI-VOD A Paint Towers 19/20	A3	N/A	CAP18365				
	WID	MR57-2021	SHEET	REVISION			
Mark Carra Assessment Daniel Ive 2002	WID	IVIN 37-202 I	1	2			
Work Scope Assessment Report - Jun-2023		WAI-VUD-A0021					

