

Structure	looking	towards	AB Face



Tower ID	WAI-VUD-A0045		
Contract number	\$2G+6		
Final No.	60-2		
Insulator Type/ Condition	COMPOSITE		
Туре	0		
Body Extn - size	0		
Legs - size	+1, -1, +/-0, +2		
Earth Wire	YES		
Tower Area m ²	122		
Rust m ²	11 9%		
Sweep m ²	89 74%		

D	WAI-VUD-A0045	RC steel identified	No				
mber	S2G+6	Earth plates fitted/ Compliant	#N/A				
).	60-2	Climbing Deterrent Fitted	YES				
Condition	COMPOSITE	Padlock Type None					
	0	Environmental Rating	Low impact on neighbouring activities, easily secured from public.				
size	0	Vehicle Access	Grass paddock or hill. Some caution needed in wet weather.				
e	+1, -1, +/-0, +2	Vegetation Control	Required Minor				
re	YES	Property Usage	Commercial				
a m²	122	Foundation Connection Type	TSC				
2	11 9%	Bridge/ Culverts	YES				
n²	89 74%	Cell Coverage	Average				

LSD - faded LSD - raded
no cpi - Fiji
CTE painted 1m up each leg
Light ZCP through out structure
Galv dross throughout structure
Structure situated in a gold mine
Heavy machinery moving round site, caution required
Site induction maybe required prior to entry, once site is up and running properly
Rird excrement throughout tower

Bird excrement throughout tower


CDG wires to be replaced
Green mould on bottom part of tower.

Clear creeper off structure
Glod mine entrance and buildings 200m from Structure





LSD on CD Face



CPI on Face





LANDOWNER DETAILS		LANDOWNER DETAILS	INSPECTION TEAM LUMEN		Date	GPS COORDINATES (WGS84)	
					17/07/2023		
	LandOwner	Refer To Efl	Inspector-Tower	Karl Formo		LATITUDE	17°42'45.72"S
	TowerAccess	Tuvatu Road - Lion One Gold Mine	Inspector-Ground	Karl Formo		LONGITUDE	177°35'11.76"E
	ContactName	Refer To Efl	Draft Report	R Glover	7/05/2025		
	ContactPhone	Refer To Efl	Report Review	M Boardman	7/05/2025		



Work Scope Assessment Report - May-2025	WAI-VUD-A0045				
Work Coops Assessment Depart May 2025		U	1	2	
	WID	0	SHEET	REVISION	
WAI-VUD-A		N/A	CAP20477		
WAI-VUD-A		DRG. SIZE		TOLDER	

