

40.50	1363	E-all	right.	Service of
	STALL.			Delta .
			100	Oleman,
		-		



Tower ID	WAI-VUD-A0024		
Contract number	HSG+9		
Final No.	67-4		
Insulator Type/ Condition	COMPOSITE		
Туре	0		
Body Extn - size	0		
Legs - size	+1, +1, +/-0, +/-0		
Earth Wire	YES		
Tower Area m ²	148		
Rust m ²	9	6%	
Sweep m ²	130	88%	

WAI-VUD	-A0024		RC steel identified	0			
HSG	+9		Earth plates fitted/ Compliant	#N/A			
67-4	4		Climbing Deterrent Fitted	YES			
COMPO	SITE		Padlock Type	None			
0			Environmental Rating	Low impact on neighbouring activities, easily secured from public.			
0			Vehicle Access	No Vehicle access directly to towers and/ or requires maintenance prior to vehicle access.			
+1, +1, +/-	-0, +/-0		Vegetation Control	Required Minor			
YES	5		Property Usage	Commercial			
148	3		Foundation Connection Type	TSC			
9	6%		Bridge/ Culverts	YES			
130	88%		Cell Coverage	Strong			
		'					

Comments
No cpi's in Fiji
CTE on all 4 legs has failed
Sharp dross throughout tower
LSD - faded

Access steep, and rutted, caution advised in the wet.
500m walk access to tower only, with steep track, covered in jungle.
River/Stream 400m off CD face
Minor construction damage on structure.


Situated in a quarry, access has to be reinstated
Two River crossing, first one be cautious, as depth of river may vary, the other is steep entry and exit, rivers may rise without warning
Some clearing around structure required

Step Bolts: 74 Comment: Minor SURFACE RUST RC Bolts 2





LSD on AB Face



CPI on na na Face





		LANDOWNER DETAILS	INSPECTION TEAM		Date	GPS COORDINATES (WGS84)	
	LANDOWNER DETAILS	LUMEN		31/03/2025	GF3 COORDINATES (WGS04)		
	LandOwner	Efl To Sort Out	Inspector-Tower	Karl Formo		LATITUDE	17°42'45.72"S
	TowerAccess	Sabeto Road	Inspector-Ground	Karl Formo		LONGITUDE	177°35'11.76"E
	ContactName	Efl To Sort Out	Draft Report	R Glover	12/02/2025		
	ContactPhone	Efl To Sort Out	Report Review	M Boardman	12/02/2025		



WAI-VUD-A		SCALE	FOL	LDER
		N/A	CAP20477	
	WID	0	SHEET	REVISION
Wards Cooks Assessment Donard Fab 2005	WID	U	1	2
Work Scope Assessment Report - Feb-2025				

WAI-VUD-A0024

